

# 03-101RHV

SPECIFICATION SHEET











6

Purple

72

**PERFORMANCE LEVEL:** 

7

Red

72

1

1

В

**PACKAGING:** 

**GLOVE SIZE** 

**CUFF COLOR** 

PER CASE

EN388: 4121A ABRASION

**PUNCTURE** 

**CUT TDM TEST** 

CUT

TEAR



8

72

2

2

2

2

C

9

72

3

3

3

3

D

10

Black

72

4

4

4

4

Ε

11

72

5

F



#### **ATTRIBUTES:**

- 15 gauge Hi-Vis Kyorene® graphene liner
- · Hi-Vis HCT® Lite nitrile palm coating

#### **FEATURES:**

- · Bacteriostatic kills harmful bacteria
- Thermal regulating to keep the hands comfortable
- · Odor neutralizing to keep the gloves smelling fresh
- · DMF and silicone free

# **APPLICATIONS:**

- · Automotive manufacturing
- · Light manufacturing
- Maintenance
- Warehousing
- Landscaping

## **CATEGORY:**

Kyorene®

### **CARE INSTRUCTIONS:**

Recommended washing temperature is between 40°C and 60°C (104°F – 140°F) with mild detergent.

The drying process may cause felting on the fabric surface. Drying temperatures should not exceed 70°C (158°F).

## **TECHNOLOGIES:**



